



**US Army Corps
of Engineers®**

Fact Sheet

DELTA AREA

Site 26.9

Critical Levee Erosion Site



Emergency Levee Repairs

Location

River: Sacramento River

River Mile: 26.9

Latitude/Longitude:

38.244045/-121.512541

Nearest Impact Area:

Walnut Grove

County: Sacramento

Bank: Left

Type of Damage

Bank erosion

Length of Repair


528 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

U.S. Army Corps of Engineers



**For further information,
please contact:**

Stan Wallin
Project Manager
U.S. Army Corps of Engineers
(916) 557-5225

Stan.J.Wallin@spk01.usace.army.mil

